


SI-35USB

Driver Installation for Windows Vista/7/8/8.1/10 (32bit/64bit)

Note: Please do not connect the converter to the USB port of PC until the procedure7 is completed.


1. Save the downloaded file to the appropriate folder and then uncompress it.
2. Run “setup.exe” file in the “nt” folder. The following message appears, and then clicks “Yes”.



3. Click “OK” to start installation of the driver package.



4. The installation wizard starts. Click “Next”.



5. Click "Install" to install the first driver.



Mark the box and this message will not show from then on.

6. The following message (Name: Serial-USB Converter Port) appears. Click "Install".



7. Click "Finish" to finish the installation of the driver package.



8. Connect the USB connector to the USB port. Then following message will appear when the PC recognizes it. This message will appear every time you connect the converter to other USB ports for the first time.



The driver Installation has completed.

The Way to Confirm the Installed Driver

From "Start" menu -> "Control Panel" -> ("Hardware and Sound" in case of Windows7), run "Device Manager".

Confirm that the name of the converter is shown in the items of Ports (COM & LPT) and Universal Serial Bus Controllers.

